



REPLY TO
ATTENTION OF:

DEPARTMENT OF THE ARMY

HEADQUARTERS, U.S. ARMY ALASKA
600 RICHARDSON DRIVE # 5000
FORT RICHARDSON, ALASKA 99505-5000



APVR-RDL-TM

AUG 23 2001

MEMORANDUM FOR SEE DISTRIBUTION

SUBJECT: Policy for Transportation of Cargo on TMP Buses (DOL/DCSLOG Policy Number 4-13)

1. Based on Army regulations it is USARAK's policy not to transport cargo on buses that cannot be hand-held, placed in the over-head cargo racks, or safely secured under the seats on TMP buses. When requested, TMP will provide additional cargo vehicles as required to transport additional cargo.
2. Hazardous material (HAZMAT) will not be transported in passenger carrying compartments of buses.
3. The OIC or NCOIC of the personnel being transported will ensure that cargo is secured as required by the motor vehicle operator. Items of cargo, when transported loosely, can become projectiles during emergency braking, or in the event of a vehicle accident. Additionally, if an aisle is cluttered with cargo, the emergency exit could be inaccessible.
4. POC for further information is Mr. Bob Koon, Chief, Motor Transport Branch, 382-2720.

FOR THE COMMANDER:

RICHARD C. NICKERSON
COL, GS
Chief of Staff

DISTRIBUTION:

A